

Inspection Photos

API: 05-043-06182

Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC

Inspection Date: 1/23/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06182 | Date: 1/23/2020

Inspection Photos



Photo 1. Facing southeast toward the location. There is debris and supplies being stored at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06182 | Date: 1/23/2020

Inspection Photos



Photo 2. There is various debris and supplies being stored at the location. The location needs to be maintained and site controlled of storage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06182 | Date: 1/23/2020

Inspection Photos



Photo 4. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06182 | Date: 1/23/2020

Inspection Photos



Photo 5. The pipe riser at the west side of the location has no LO/TO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06182 | Date: 1/23/2020

Inspection Photos



Photo 6. Facing northeast at the location. There are tires and various supplies stored at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06182 | Date: 1/23/2020