



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 263485 Type: WELL API Number: 123-20901 Status: TA Insp. Status: WK

**Workover**

Comment: MIRU Ranger Energy Services e-line, RIH with guagering/junkbasket combination to 7210' KB, POOH with guagering/junkbasket, RIH and run CBL from 3000' KB to surface, RIH with 4 1/2" 10K CIBP and set @ 6995' KB, POOH with setting tool, RIH with dumpbailer and spot 2 sxs of cement slurry on top of CIBP, POOH with dumpbailer, RIH with jetcutter and cut csg @ 2500' KB, POOH with spent cutter, RDMO e-line.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696501571	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5049201">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5049201</a>