



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Jan 19, 2020 9:05:37 PM MST
Server Receive Date:	Jan 19, 2020 9:05:42 PM MST
Reference Number:	20200120-18130057616
Location:	16A Road 51921, Bloomfield, NM 87413, USA
	Jan 19, 2020 8:54:48 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Well Name	ANNALA FEDERAL GAS UNIT A 1
API Number	50670774100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down

Photo of first corrective action completed



Completed work description Corrective Action 1

Installed rock check dams on erosion channel

Photo of second corrective action completed



Completed work description of corrective action 2

Photo of third corrective action completed



Completed work description of corrective action 3

Installed silt bowl with rock armored run down

Photo of fourth corrective action completed



Completed work description of corrective action 4

Replaced muffler flex pipe

Additional photos



Summary of all work completed

Installed rock check dams on erosion channel.
Installed silt bowl with rock armored run down.
Cleaned up stained soils around the wellhead.
Replaced muffler flex pipe on pumping unit.