

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2020

Submitted Date:

01/28/2020

Document Number:

693200554**FIELD INSPECTION FORM**Loc ID 322352 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		regulatory@foundationenergy.com	All inspections
McFarland, Nick		nick.mcfarland@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210347	WELL	SI	08/04/2009	GW	045-06103	FEDERAL 23-12	PA

General Comment:[Engineering Integrity Inspection performed on January 24 2020. In response to Form 6 Document number 401846973](#)

Inspected Facilities

Facility ID: 210347 Type: WELL API Number: 045-06103 Status: SI Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: Other Material:
 Variance: No Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Operator added note in form 6 document number 401846973

Note - The Federal 23-12 was never hooked up to a pipeline, and no flowlines were ever laid that would need to be abandoned. Due to this, a form 42 flowline abandonment will not be submitted.

Operator reported on form 7 gas production from January 1999 to June 2005.

Previous inspection dated 3/21/2018 document number 690300234 and inspection dated 3/27/2018 document number 680402546. Have pictures documenting flowlines to wellhead.

Photo log attached

Corrective Action: Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200556	Foundation 322352	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5050236