

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2020

Submitted Date:

01/28/2020

Document Number:

689704107

FIELD INSPECTION FORM

Loc ID 335594 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|-------|--|---------------------------|
| , Caerus Piceance | | COGCC.inspections@caerus oilandgas.com | Piceance inspections only |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 281254 | WELL | PR | 11/14/2006 | GW | 045-11414 | N.PARACHUTE EF 16D H29A 595 | PR |
| 281255 | WELL | PR | 02/01/2014 | GW | 045-11415 | N.PARACHUTE EF 15B H29A 595 | PR |
| 281256 | WELL | PR | 11/10/2005 | GW | 045-11416 | N.PARACHUTE EF01B H29A 595 | PR |
| 281257 | WELL | PR | 11/24/2006 | GW | 045-11417 | N.PARACHUTE EF16B H29A 595 | PR |
| 281258 | WELL | PR | 11/03/2006 | GW | 045-11418 | N.PARACHUTE EF09B H29A 595 | PR |
| 281259 | WELL | PR | 11/08/2006 | GW | 045-11419 | N. PARACHUTE EF01D H29A 595 | PR |
| 281260 | WELL | PR | 11/10/2005 | GW | 045-11420 | N.PARACHUTE EF 15D H29A 59 | PR |
| 281261 | WELL | PR | 02/01/2014 | GW | 045-11421 | N.PARACHUTE EF 10D H29A 595 | PR |

General Comment:

This is a summary of inspection report.
On Tuesday 01/28/2020 at approximately 1100 hours, I, Inspector Mike Longworth, conducted a field inspection at CAERUS PICEANCE LLC N.PARACHUTE-65S95W 29SENE H29A , at Location # 335594 in Garfield County, Colorado

Location

| | | | |
|--------------------|------|--|-------|
| Lease Road: | | | |
| Type | Main | | |
| comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------------|------------|--|-------|
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|-----|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|-------|--|-------|
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

Multiple Spills and Releases?


| | | | |
|--------------------|-----|--|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 8 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|----|--|-------|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------|--|--|--|
| Flaring: | | | |
| Type | | | |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 281254 | Type: | WELL | API Number: | 045-11414 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281255 | Type: | WELL | API Number: | 045-11415 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281256 | Type: | WELL | API Number: | 045-11416 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281257 | Type: | WELL | API Number: | 045-11417 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281258 | Type: | WELL | API Number: | 045-11418 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281259 | Type: | WELL | API Number: | 045-11419 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281260 | Type: | WELL | API Number: | 045-11420 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281261 | Type: | WELL | API Number: | 045-11421 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |



Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Berms | | | | | | |
| Compaction | | | | | | |
| | | Ditches | | | | |
| | | Compaction | | | | |
| | | | | Material Handling And Spill Prevention | Pass | |

Comment: Limited BMP inspection due to snow cover.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 689704111 | Inspection 689704107 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051041 |