

Inspection Photos
Operator: BP America
Location/API #: 067-06982
Date: 1-28-2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of western project area from the northwestern corner facing southward. Revegetation is largely dormant but appears to be comprised of grasses such as western wheatgrass, smooth brome, and crested wheatgrass.



Photo 3. View of revegetation within the eastern project area comprised of dense rubber rabbitbrush.



Photo 4. View of the reference area in background comprised of open grass field with scattered pinyon and juniper trees.