

Inspection Photos
Operator: BP America
Location/API #: 067-09610
Date: 1-28-2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing southward. Revegetation is largely dormant but appears to be comprised of grasses such as intermediate wheatgrass, smooth brome, and crested wheatgrass.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of the reference area in background comprised of open grass field with scattered pinyon and juniper trees, largely snow covered at this time.