

Inspection Photos

1/28/2020

Operator: CHEVRON USA INC # 16700

Location ID: 398839

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CHEVRON USA INC # 16700
Location ID: 398839



20200128

40.14138° N 108.85726° W

Photo 1: Photo taken from the west end of the active wells, facing east. Photo shows all 3 of the active wells have been drilled in proximity of one another. 4th well on location "AL"; unable to find evidence that well was drilled.



20200128

40.14138° N 108.85729° W

Photo 2: Photo of well API 103-11501. Form 5(F) No. 400310065 shows "as drilled" records to be "40.141068/-108.857048", or the southeast corner of the pad; See comments under photo 11. "As drilled" records in correct, well located within central area of the Location. Updated "as drilled" records will need to be submitted.

Inspection Photos
Operator Name: CHEVRON USA INC # 16700
Location ID: 398839



Photo 3: Photo taken from the east end of the location, facing south. Photos 3-6 provide an overview of the Location from south, southwest, northwest to north. Photos also show areas of the production area beyond the anchors that do not appear to be reasonably needed for production activities, and needs to be reclaimed in accordance with Rule 1003.b. Photo also shows soil stockpile on the southeast corner of the Location.

Photo 4: See comments under photo 3. Arrow shows easternmost anchor.

Inspection Photos
Operator Name: CHEVRON USA INC # 16700
Location ID: 398839



Photo 5: See comments under photo 3. Arrow shows easternmost anchor



Photo 6: See comments under photo 3. Photo also shows soil stockpile on the northeast end of the Location. Soil stockpile appears exposed and unstabilized on the visible slopes.

Inspection Photos
Operator Name: CHEVRON USA INC # 16700
Location ID: 398839



Photo 7: Photo of gravel pile stored on Location west of the wells.



Photo 8: Photo of barrier in disrepair on the northwest end of the location.

Inspection Photos
Operator Name: CHEVRON USA INC # 16700
Location ID: 398839



Photo 9: Photo taken from the west end of the location, facing northeast. Photo 9-10 provide an overview of the location from northeast, to southeast.

Photo shows areas of the production area beyond the anchors that do not appear to be reasonably needed for production activities, and needs to be reclaimed in accordance with Rule 1003.b.



Photo 10: Photo shows stained soils remain at the base of the tank.

Inspection Photos
Operator Name: CHEVRON USA INC # 16700
Location ID: 398839



Photo 11: COGIS aerial imagery of wells on Location. Photo shows “As drilled” location for API 103-11501 is incorrect.

Inspection Photos
Operator Name: CHEVRON USA INC # 16700
Location ID: 398839



Photo 12: 2006 Google Earth aerial imagery. Photo shows Location prior to the Location's O&G disturbance.

Inspection Photos
Operator Name: CHEVRON USA INC # 16700
Location ID: 398839



Photo 13: 2015 Google Earth aerial imagery; most current google imagery. Photo shows the soil stockpile on the northeast and southeast ends of the Location. Photo also shows approximate areas of the current production area beyond the anchors that do not appear to be reasonably needed for production activities