

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2020

Submitted Date:

01/29/2020

Document Number:

696200922

FIELD INSPECTION FORM

Loc ID 316636 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 100 CHEVRON ROAD
City: RANGELY State: CO Zip: 81648

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		atlx@chevron.com	
		SPWU@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290291	WELL	PR	10/01/2019	OW	103-11010	FAIRFIELD KITTI A 5P	RI
316636	LOCATION	AC			-	FAIRFIELD KITTI A-62N102W 17SEW	RI

General Comment:

On 1/28/2020, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at CHEVRON USA INC # 16700's FAIRFIELD KITTI A location in Rio Blanco County, Colorado.

It was documented that Location appears to comport with 1003 rules, however snow cover on the surface and interim areas of the Location prevented reclamation specialist to conduct an accurate assessment of the Reclamation.

Refer to the "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 290291 Type: WELL API Number: 103-11010 Status: PR Insp. Status: RI

Producing Well

Comment: PR Well, IR and SW inspection

Corrective Action:

Date:

Facility ID: 316636 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment [Based on historic aerial imagery, remaining soils \(possibly excavated durring construction activities\) are stored on the west end of the Location.](#)

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment [Location and interim areas covered in snow at time of inspection; a follow-up inspection will be conducted to determine compliance with Rule 1002.c](#)

Corrective Action _____

Date _____

1002E. SURFACE DISTRURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment [No waste or debris found on location or reclamation area.](#)

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment [No unused/unneeded equipment/materials found being stored on location or reclamation area.](#)

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment [Anchors marked in accordance with Rule 1003.a](#)

Corrective Action _____

Date _____

Corrective Action: <input type="text"/>	Date <input type="text"/>	
Overall Final Reclamation <input type="checkbox"/>	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696200923	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5052287