

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/29/2020

Submitted Date:

01/29/2020

Document Number:

679707141

FIELD INSPECTION FORM

Loc ID 314290 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 200323
Name of Operator: PICEANCE CREEK RANCH LTD
Address: 11539 CO RD 5
City: RIFLE State: CO Zip: 81650

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Johnson, Dan	970-878-5103	piceance@dishmail.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228243	WELL	DM	05/06/1955	GW	103-05065	CLUBINE ERIC 2	DM

General Comment:

[COGCC Inspection Report Summary.](#)

On 1-29-2020 at approximately 12:45, inspector Rick Moran, conducted a follow up inspection at Piceance Creek Ranch well Eric Clubine 2 in Rio Blanco county of FIR document 679705820.

The following compliance issues were resolved:
1) Well head sign missing "911" and nearest county road.
2) Remove fuel container & rusty barrel from location.

This is a summary of inspection report 679707141.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911		
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:

					corrective date
Type: Bird Protectors	# 1				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heater Treater	# 1				
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 228243 Type: WELL API Number: 103-05065 Status: DM Insp. Status: DM

Producing Well

Comment: The inspector was unable to determine if the well was producing at the time of inspection.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679707142	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5052439