

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/29/2020

Submitted Date:

01/29/2020

Document Number:

679707143

**FIELD INSPECTION FORM**

Loc ID 314291 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 200323  
Name of Operator: PICEANCE CREEK RANCH LTD  
Address: 11539 CO RD 5  
City: RIFLE State: CO Zip: 81650

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Johnson, Dan	970-878-5103	piceance@dishmail.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228244	WELL	DM	08/18/1954	GW	103-05066	CLUBINE, ERIC 1	DM

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 1-29-2020 at approximately 12:50, inspector Rick Moran, conducted a follow up inspection at Piceance Creek Ranch well Eric Clubine 1 in Rio Blanco county of FIR document 679705818.

The following compliance issues were resolved:  
1) Well head sign missing "911" and nearest county road.

This is a summary of inspection report 679707143.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

**Emergency Contact Number:**

Comment:	911		
Corrective Action:			Date: _____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

**Equipment:**

			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 228244 Type: WELL API Number: 103-05066 Status: DM Insp. Status: DM

**Producing Well**

Comment: The inspector was unable to determine if the well was producing at the time of inspection.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679707144	inspection photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5052440">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5052440</a>