

# Interim Reclamation and Stormwater Inspection

January 28, 2020

Operator: HIGHPOINT OPERATING CORPORATION- 10071

Location ID: 416448

Inspection Document #: 697501075

Weld County, CO

NWNW Section 35 T12N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Fox Creek #1-35H  
Location ID: 416448



**Photo 1.** Photo taken from the northwestern location, facing Southeast. Photo illustrates Operator has installed additional BMPs (stabilized berm, erosion control blankets and wattles) along the western perimeter of the location in response to the previous corrective action inspection.

Inspection Photos  
Location Name: Fox Creek #1-35H  
Location ID: 416448



**Photo 2.** Photo taken from the western location, facing Southeast. See comments under Photo 1.

Inspection Photos  
Location Name: Fox Creek #1-35H  
Location ID: 416448



**Photo 3.** Photo taken from the southwestern location, facing Southeast. See comments under Photo 1.

## Inspection Photos

Location Name: Fox Creek #1-35H

Location ID: 416448



**Photo 4.** Photo taken from the southwestern perimeter of location, facing Northwest. Photo illustrates Operator has not yet performed reclamation activities associated with stormwater erosion degrading vegetation off location. Operator will be responsible for reclaiming this disturbance and should further reclamation activities the next available seeding opportunity.



**Photo 5.** Photo taken from the southwestern perimeter of location, facing Northwest. See comments under Photo 4.

Inspection Photos  
Location Name: Fox Creek #1-35H  
Location ID: 416448




**Photo 6.** Photo taken along the western perimeter of location, facing Northwest. See comments under Photo 4.



**Photo 7.** Photo taken along the western perimeter of location, facing Northwest. See comments under Photo 4.

Inspection Photos  
Location Name: Fox Creek #1-35H  
Location ID: 416448



**Photo 8.** Photo taken from the southwestern interim reclamation area, facing Southeast. Photo illustrates vegetative growth within the interim reclamation area (intermediate wheatgrass and smooth brome) is not reflective of reference area vegetation (blue gramma and sand dropseed).

Inspection Photos

Location Name: Fox Creek #1-35H

Location ID: 416448



**Photo 9.** Photo taken from the southwestern guy line anchor, facing North. Operator shall properly mark anchor per Rule 1003.a.



**Photo 10.** Photo taken from the southeastern guy line anchor, facing Northeast. Photo illustrates this guy line anchor is sufficiently marked per Rule 1003.a.