

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2020

Submitted Date:

01/30/2020

Document Number:

699100991**FIELD INSPECTION FORM**Loc ID 451243 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@extracti onog.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451240	WELL	DG	04/13/2019		123-45035	AD FED DOUBLE CLUTCH 20W-25-8	DG

General Comment:

Inspected Facilities

Facility ID: 451240 Type: WELL API Number: 123-45035 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Ensign 147 Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: _____
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: Waste Connections

Comment: Current status was TOO H after performing BOP Test.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
COGCC Inspection Report Summary On Thursday 1/30/20 at approximately 1056 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at AD Fed Double Clutch 20W-25-08 of Extraction Oil & Gas, at API # 05-123-45035 in Weld County in Colorado. While there, I observed drilling operations by Ensign 147. Current status was TOO H after performing BOP Test. No violation of COGCC rules were observed at the time of inspection. This is a summary of inspection report. Continuing education inspections	burnsa	01/30/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699100992	Inspection	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5053217