

Inspection Photos  
Operator: BP America  
Location/API #: 067-06651  
Date: 1-28-2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing within areas that are not weed infested (see below), with grasses such as sand dropseed and smooth brome.





Photo 3. View of dense musk thistle debris within the southwestern project area. Weeds are not controlled.





Photo 4. View of Russian knapweeds within the western project area.





Photo 5. View of the reference area comprised of mixed sagebrush shrubland and pinyon and juniper woodland.