

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2020

Submitted Date:

01/31/2020

Document Number:

689704151**FIELD INSPECTION FORM**Loc ID 335457 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268848	WELL	PR	02/17/2004	OW	045-09304	CHEVRON GM 332-20	PR
268909	WELL	PR	07/30/2003	OW	045-09312	CHEVRON GM 333-20	PR
283747	WELL	PR	08/09/2006	GW	045-11986	CHEVRON GM 422-20	PR
283748	WELL	PR	08/13/2006	GW	045-11987	CHEVRON GM 532-20	PR
283749	WELL	PR	03/10/2006	GW	045-11988	CHEVRON GM 432-20	PR

General Comment:

On Friday 01/31/2020 at approximately 1310 hours, I, Inspector Mike Longworth, conducted a field inspection at Terra Rocky Mountain LLC CHEVRON-66S96W 20SWNE, at Location # 335457 in Garfield County, Colorado

Location				
Lease Road:				
Type	Access			
comment:	Snow Covered			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	TRASH			
Comment:				
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Equipment:				
Type: Plunger Lift	# 1			corrective date
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:



Inspected Facilities									
Facility ID:	268848	Type:	WELL	API Number:	045-09304	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	268909	Type:	WELL	API Number:	045-09312	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	283747	Type:	WELL	API Number:	045-11986	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	283748	Type:	WELL	API Number:	045-11987	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	283749	Type:	WELL	API Number:	045-11988	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				
		Compaction				
Compaction						
Ditches						

Comment: [Limited BMP inspection due to snow cover.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704152	Inspection 689704151 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055046