

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/31/2020

Submitted Date:

01/31/2020

Document Number:

679707177

**FIELD INSPECTION FORM**

Loc ID 314960 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone        | Email                   | Comment                            |
|--------------|--------------|-------------------------|------------------------------------|
| Reid, Jordan | 970-563-4000 | maralextechjr@gmail.com | <a href="#">All inspections</a>    |
| Graves, Jim  | 970-712-0099 | mrinc20@qwestoffice.net | <a href="#">Operations Manager</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 229980      | WELL | PR     | 09/07/1995  | GW         | 103-07639 | SOLDIER CANYON 26-1 | PR          |

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 1-31-2020 at approximately 12:05, inspector Rick Moran, conducted a follow up inspection at Maralex Soldier Canyon 26-1 in Rio Blanco county of FIR document 679706050.

The following compliance issues were resolved:

- 1) Missing well head sign.

This is a summary of inspection report 679707177.

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |     |       |  |
|--------------------|-----|-------|--|
| Type               | PIT |       |  |
| Comment:           |     |       |  |
| Corrective Action: |     | Date: |  |

**Equipment:**

| Type                        | #   |       | corrective date |
|-----------------------------|-----|-------|-----------------|
| Bird Protectors             | # 1 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |
| Deadman # & Marked          | # 3 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |
| Horizontal Heated Separator | # 1 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |
| Gas Meter Run               | # 1 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |

**Tanks and Berms:**

| Contents       | #                    | Capacity  | Type     | Tank ID | SE GPS                |
|----------------|----------------------|-----------|----------|---------|-----------------------|
| PRODUCED WATER | 1                    | <100 BBLS | Open Top |         | 39.661010,-108.704740 |
| Comment:       | <input type="text"/> |           |          |         |                       |

|                    |       |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

**Paint**

|                  |          |  |  |
|------------------|----------|--|--|
| Condition        | Adequate |  |  |
| Other (Content)  |          |  |  |
| Other (Capacity) | 90 bbl   |  |  |
| Other (Type)     |          |  |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 229980 Type: WELL API Number: 103-07639 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat: 39.673180                      Long: -108.699590

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: Wildlife                      Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: \_\_\_\_\_                      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

Anchor Trench Present: \_\_\_\_\_                      Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 679707178    | inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055151">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055151</a> |