

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2020

Submitted Date:

02/01/2020

Document Number:

696102074**FIELD INSPECTION FORM**Loc ID 331694 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265014	WELL	PA	07/28/2017	GW	123-21139	WELLS RANCH 14-35	PA

General Comment:[This is a PLUGGED & ABANDONED WELL / ABANDONED BATTERY inspection.](#)[Well\(s\): 1: Plugged & Abandoned | PA.](#)[Battery: Abandoned. ALL equipment removed.](#)[Reclamation progressing.](#)[Abandoned Battery SE corner GPS coordinates: 40.437720, -104.411023](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date:

Type: Plunger Lift

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date:

Type: Pig Station

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date:

Type: Ancillary equipment

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date:

Type: Gas Meter Run

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment: Plugged & Abandoned PA. Equipment removed.					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

PaintCondition: Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:							
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	0				,		
Comment:		Plugged & Abandoned PA. Equipment removed.					
Corrective Action:							Date:

Paint

Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:							
		Date:					

Venting:

Yes/No							
Comment:							
Corrective Action:						Date:	

Flaring:

Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities

Facility ID: 265014 Type: WELL API Number: 123-21139 Status: PA Insp. Status: PA

Workover

Comment: Plugged & Abandoned | PA.
Well appears to be cut / capped.
Form 6 doc. #401397003 indicates plugging date: 07/28/2017. Approved.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On SAT 02/01/2020 at approximately 09:28 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: WELLS RANCH-66N63W /35SWSW Location ID: 331694 Well Name: Wells Ranch 14-35 API: 05-123-21139 Location County: Weld County, Colorado Weather: Partly cloudy.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment removed. Reclamation progressing. Abandoned Battery SE corner GPS coordinates: 40.437720, -104.411023</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/01/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102075	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055201