

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2020

Submitted Date:

02/04/2020

Document Number:

688800666**FIELD INSPECTION FORM**Loc ID 333833 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Heil, John		john.heil@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215045	WELL	PR	12/15/1982	GW	067-06650	ROBERTSON 19-01 1	EI
216417	WELL	PR	10/02/2014	GW	067-08023	STATE COM BZ 2	EI

General Comment:

On January 30, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Robertson 19-01 #1. For the most recent field inspection report of this facility, please refer to document #687905872.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Tank is labeled with contents, capacity, and has NFPA placard.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Free standing sign near location entrance.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	STORAGE OF SUPL			
Comment:	Joint of 6" steel pipe stored on location. Section of pipeline recently replaced as a result of Spill/Release Point ID #470891, adjacent to this location.			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Stock panel enclosure around well heads.			
Corrective Action:				Date:
Type	LOCATION			
Comment:	Perimeter fencing.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Stock panel fencing around telemetry, separator, and meter house.			
Corrective Action:				Date:
Equipment:				
Type: Other	# 2			corrective date
Comment:	Linear rod pumps.			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV STEEL		37.086603,-107.537320
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	21 bbl.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>215045</u>	Type:	<u>WELL</u>	API Number:	<u>067-06650</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>216417</u>	Type:	<u>WELL</u>	API Number:	<u>067-08023</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Rip Rap	Pass					
Ditches	Pass					
Gravel	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On January 30, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Robertson 19-01 #1. For the most recent field inspection report of this facility, please refer to document #687905872. Equipment and supplies stored on location while Spill/Release Point ID #470891 repairs are made.	hughesjo	02/04/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800667	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5056541