

Inspection Photos
Location Name: Robertson 19-01 #2
API: 05-067-08778



Lube oil container on secondary containment.



Lube oil staining on equipment and surrounding gravel.

Inspection Photos
Location Name: Robertson 19-01 #2
API: 05-067-08778



Production equipment is currently shut in while repairs are made to gathering system following Spill/Release Point ID #470891.



95 bbl. produced water PBV.