

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/04/2020

Submitted Date:

02/04/2020

Document Number:

700700065**FIELD INSPECTION FORM**
 Loc ID 334931 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271507	WELL	PR	08/02/2004	GW	045-09893	BENZEL 1-5C (P35B)	PR
271509	WELL	PR	08/01/2004	GW	045-09891	BENZEL 36-13C (P35B)	PR
271626	WELL	PR	12/15/2004	GW	045-09915	BENZEL 35-15A (P35B)	PR
272187	WELL	PR	08/08/2004	GW	045-10036	BENZEL 35-9A1 (P35B)	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 2/4/20 at approximately 9:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus P35B, at Location # 334931 in Garfield Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 271507	Type: WELL	API Number: 045-09893	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 271509	Type: WELL	API Number: 045-09891	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 271626	Type: WELL	API Number: 045-09915	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 272187	Type: WELL	API Number: 045-10036	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:			Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700070	700700065	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5056933