

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2020

Submitted Date:

02/05/2020

Document Number:

700900011**FIELD INSPECTION FORM**Loc ID 320247 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, KPK		cogcc@kpk.com	All KPK Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203223	WELL	PR	02/19/2008	GW	001-08732	RUEBEL ET AL 1-3	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Vinyl		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Vinyl		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter out of calibration		
Corrective Action:	Meter needs to be calibrated per Rule #329. See photo #1	Date:	03/02/2020
Type: Bradenhead	# 1		

Comment:	Apperes to be plumbed to surface		Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	#			
Comment:	Stained soil under separator. Control and contain spills/releases and clean up per Rule 906.a.		Date:	
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. See photo #2		Date:	03/02/2020

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		39.998263,-104.617790
Comment:	Bull plug missing from loadoff line.				
Corrective Action:	Location is within a designated setback location, bullplug or cap all loadlines per Rule #604.c.(2)O. See photo #3				Date: 02/17/2020

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Shares burm with produced water			
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	30bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				

Venting:

Yes/No	NO
Comment:	
Corrective Action:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 203223 Type: WELL API Number: 001-08732 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: Appears to be plumbed to surface

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday January 28, 2020 at approximately 9:59am, I, Inspector Chane Finkenbinder, Conducted an on-site inspection at Ruebel ET AT #1-3, KP Kauffman at Location # 320247, API # 001-08732 in Adams County Colorado.</p> <p>While there, I observed Production well, during this inspection the following possible compliance issues were observed:</p> <p>Meter out of calibration. Meter needs to be calibrated per Rule #329 see photo# 1. Corrective action Date 03/02/2020.</p> <p>Bull plug missing from loadoff line. Location is within a designated setback location, bullplug or cap all loadlines per Rule #604.c.(2)O. Corrective action Date 2/17/2020 See attached photo #3.</p> <p>Stained soil under separator. Control and contain spills/releases and clean up per Rule 906.a. See photo #2. Corrective action date 03/02/2020.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	01/29/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900012	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5058520