

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/06/2020

Submitted Date:

02/06/2020

Document Number:

698700970

FIELD INSPECTION FORM

Loc ID 322887 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244423	WELL	SI	11/01/2018	GW	123-12217	BAUER 9-1	SI

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	BV CONCRETE		,	
Comment: Shares containment with crude oil tank						
Corrective Action:						Date:

Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						Date:
Corrective Action:						Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						Date:
Corrective Action:						Date:

Venting:						
Yes/No	NO					
Comment:						Date:
Corrective Action:						Date:

Flaring:						
Type						
Comment:						Date:
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 244423 Type: WELL API Number: 123-12217 Status: SI Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On (2/6/2020) at approximately (10:55 AM), I, (Abe Serna), Conducted an on-site inspection at (Bauer #9-1) (Noble Energy), at (Location # (322887) in (Weld) Colorado. While there, I observed (SI Well) During this inspection no compliance issues were observed: No follow up on this site inspection needs to be conducted. This is a summary of inspection report. Continuing Inspector Training.</p>	sernaa	02/06/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698700971	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060063