

Inspection Photos
Location Name: Johnson, Rolland A-1 & TB
Location ID: 332889



Photo 1 WH sign

Photo 2 PU

Inspection Photos
Location Name: Johnson, Rolland A-1 & TB
Location ID: 332889



Photo 3 stained soil around WH

Photo 4 Stained soil possible leak under swedge on backside of crude oil tank

Inspection Photos
Location Name: Johnson, Rolland A-1 & TB
Location ID: 332889



Photo 5 TB sign PW tank sign shows 50 bbl

Photo 6 PW tank shows 100 bbl

Inspection Photos
Location Name: Johnson, Rolland A-1 & TB
Location ID: 332889



Photo 7 TB

Photo 8 Horizontal heated Separators berm is not properly maintained

Inspection Photos
Location Name: Johnson, Rolland A-1 & TB
Location ID: 332889



Photo 9 Gas meter run

Photo 10 flow lines & valves bull plugged no LOTO

Inspection Photos
Location Name: Johnson, Rolland A-1 & TB
Location ID: 332889



Photo 11 Manifold and flow lines bull plugged no LOTO