

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/07/2020

Submitted Date:

01/31/2020

Document Number:

688800664**FIELD INSPECTION FORM**Loc ID 320887 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 69805Name of Operator: PETROX RESOURCES INCAddress: 12600 W COLFAX AVENUE #C-440City: LAKEWOOD State: CO Zip: 80215**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	
Clark, Ryan		ryan@petrox-resources.com	
Clark, Mike	970-878-5594	mike.petroxcbm@gmail.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
Nystrom, Dusty	505-330-1328	nystrow@yahoo.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279975	WELL	PR	03/01/2016	GW	007-06215	CANDELARIA 33-5 FEE 10U #3	EI

General Comment:

On January 31, 2020 COGCC Reclamation Specialist Catherine Roy and SW EPS Jim Hughes conducted a joint inspection of the Petrox Resources Inc. Candelaria 33-5 Fee #10U #3. For the most recent field inspection report of this facility, please refer to document #693900918.

Location			
Lease Road:			
Type	Main		
comment:	Forest Service Road 613.		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near pump jack.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	"T" posts and electric fence holders near pump jack.		
Corrective Action:	Comply with Rule 603.f.		Date: 02/28/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Perimeter fence. Gate was open upon arrival.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Hog wire fence around well head and pump jack.		
Corrective Action:			Date:
Equipment:			
Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			

Inspector Name: Hughes, Jim

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	279975	Type:	WELL	API Number:	007-06215	Status:	PR	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	In Process	Secondary containment for lube oil container.

Comment: Secondary containment for lube oil container is almost full of ice.Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.1.

Date: 02/28/2020

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On January 31, 2020 COGCC Reclamation Specialist Catherine Roy and SW EPS Jim Hughes conducted a joint field inspection of the Petrox Resources Inc. Candelaria 33-5 Fee #10U #3. For the most recent field inspection report of this facility, please refer to document #693900918.</p> <p>During this inspection the secondary containment device for the lube oil container was observed to be almost full of ice.</p> <p>Fencing supplies are being stored near the pump jack.</p> <p>Staining was observed on the well head cover.</p>	hughesjo	01/31/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402300789	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5054983
688800665	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5054976