

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/05/2020

Submitted Date:

02/07/2020

Document Number:

690101724

**FIELD INSPECTION FORM**

Loc ID 321503 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCInspections@extractionog.com	
Canfield, Chris		chris.canfield@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203303	WELL	PR	05/31/2008	GW	014-08812	BROZOVICH MA 8-8J	EG
471108	SPILL OR RELEASE	CL	01/30/2020		-	BROZOVICH-61S68W 8SENE	EG

**General Comment:**

Engineering integrity inspection performed on February 5th, 2020 in response to initial form 19 spill report Doc #402298887 received by COGCC on 01/30/2020 that outlines: While removing a partially-buried produced-water vessel at the BROZOVICH-61S68W 8SENE (Location ID: 321503), legacy suspected soil impacts were observed. On Jan 30, 2020 the reporting threshold of impacted soil was reached.

Details of observations made during this field inspection are located in the flowline and comment sections of this report. Photos uploaded.

**Inspected Facilities**

Facility ID: 203303 Type: WELL API Number: 014-08812 Status: PR Insp. Status: EG

Facility ID: 471108 Type: SPILL OR API Number: - Status: CL Insp. Status: EG

**Flowline**

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: \_\_\_\_\_ Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Well (BROZOVICH MA 8-8J) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #402241253 received on 11/16/2019. No Extraction or contract personnel were on location at the time of this field inspection. Excavation and remediation work appears to be nearing completion. Equipment/ tanks have been removed. No flowline risers were observed on location during this field inspection at wellhead or facility/ battery areas.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
As outlined in the CA section of COGCC form 19 Doc#402298887: While removing a partially-buried produced-water vessel, legacy soil impacts were observed in the sidewalls and base of the excavation. It appears that equipment failure in the base or sidewalls of the vessel resulted in a release of fluids and soil impacts. The entire site is being decommissioned and will be reclaimed.	maclarej	02/07/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101725	Location photo (view east)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060954">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060954</a>
690101726	Gas gathering pipeline marked (pin flagged)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060955">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060955</a>