

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/03/2020

Submitted Date:

02/03/2020

Document Number:

679707195**FIELD INSPECTION FORM**Loc ID 311853 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10384Name of Operator: GENESIS GAS & OIL COLORADO LLCAddress: 1660 LINCOLN ST STE 2100City: DENVER State: CO Zip: 80246**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kimmel, March	210-363-2859	mkimmel@headwatersexp.com	
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286511	WELL	SI	12/04/2013	GW	103-10888	FLETCHER GULCH 3-31	TA

**General Comment:**[COGCC Inspection Report Summary.](#)

On 2-3-2020 at approximately 8:15, inspector Rick Moran, conducted a follow up inspection at Genesis Gas &amp; Oil Colorado well Fletcher Gulch 3-31 in Rio Blanco county of FIR document:

1) 679704940, dated 7-31-2019.

The following compliance issues are uncompleted:

- 1) Missing "911" on battery sign. Photos 8 & 9. Complete by 9-30-2019.
- 2) Holes in tank liner. Photos 10 & 11. Complete by 8-30-2019.
- 3) Stained soil. Photos 12 & 13. Complete by 8-30-2019.
- 4) Tank labels missing operator name & phone number. Photo 14 & 15. Complete by 9-30-2019.

Additional compliance issues:

- 1) Weed debris. Photos 3, 4, 5, 6, 7. Complete by 3-4-2020.
- 2) No current MIT on file.

A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679707195.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label missing operator name & phone number.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/30/2019

Emergency Contact Number:

Comment: Missing "911" on battery sign.

Corrective Action: Install sign to comply with Rule 210.b. Date: 09/30/2019

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Weed debris on location and vegetation next to pump jack & meter building.		
Corrective Action:	Comply with Rule 603.f .	Date:	03/04/2020
Type	OTHER		
Comment:	Stained soil next to tank. Due to snow cover, the inspector was unable to determine if a clean up had occurred since the last inspection.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/30/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	Two pumps on skids and 1 equipment building.		
Corrective Action:		Date:	

Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	400 BBLs	STEEL AST		40.083200,-108.609900	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal				Inadequate	
Comment:	~50 holes in liner.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).				Date: 08/30/2019

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 286511 Type: WELL API Number: 103-10888 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last recorded production December 2012. Last MIT on 12-12-2014.No current MIT on file.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402302117	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5056072">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5056072</a>
679707196	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5056054">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5056054</a>