

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402046077

Date Received:

05/16/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 5 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Church, Matt

405-651-6853

mchurch@sandridgeenergy.com

Neidel, Kris

kris.neidel@state.co.us

sandridgeenvironmental@sandridgeenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692400970

Inspection Date: 05/08/2019

FIR Submit Date: 05/14/2019

FIR Status: _____

Inspected Operator Information:

Company Name: SANDRIDGE EXPLORATION & PRODUCTION LLC

Company Number: 10598

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

LOCATION - Location ID: 447512

Location Name: Open Range Number: 18 County: _____

Qtrqr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6

Latitude: 40.571594 Longitude: -106.424475

FACILITY - API Number: 05-057-00 Facility ID: 447512

Facility Name: Open Range Number: 18

Qtrqr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6

Latitude: 40.571594 Longitude: -106.424475

CORRECTIVE ACTIONS:

1 ☒ CA# 125144

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 05/15/2019

24 hours to remove free fluids. 30-days to remove stained soil.

Response: CA COMPLETED

Date of Completion: 05/13/2019

Mouse holes were backfilled and capped. All fluids were removed via hydro vac prior to backfill and capping.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 125145

Corrective Action: Stabilize stockpiled soil with appropriate BMPs or remove from site if determined by identification to be necessary.

Date: 05/29/2019

Response: CA COMPLETED

Date of Completion: 05/13/2019

Operator
Comment:

Piles were of snow and base material from clearing pad of snow. Piles were spread out so ice and snow could melt.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 125146

Corrective Action: Protect and stabilize with appropriate BMPs, stockpiled soil.

Date: 05/29/2019

Response: CA COMPLETED

Date of Completion: 05/13/2019

Operator
Comment:

Piles were of snow and base material from clearing pad of snow. Piles were spread out so ice and snow could melt.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 125147

Corrective Action: Close/backfill two open mouse holes.
CA Date given is thirty days past date of Release of Drilling Rig.

Date: 12/24/2018

Response: CA COMPLETED

Date of Completion: 05/13/2019

Operator
Comment:

Mouse holes were backfilled and capped. All fluids were removed via hydro vac prior to backfill and capping.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Church

Signed: _____

Title: EHS Specialist

Date: 5/16/2019 8:05:32 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402046077	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files