

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/11/2020

Submitted Date:

02/11/2020

Document Number:

700700125**FIELD INSPECTION FORM**Loc ID 322316 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 1660 LINCOLN STREET SUITE 1450

City: DENVER State: CO Zip: 80264

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, mustang	303-807-5112	dlemon@mustangresourcesllc.com	regulatory manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210267	WELL	PR	12/01/2016	GW	045-06023	JUHAN FEE 26-94-6S-94W	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 2/11/20 at approximately 1:00 PM, I, Inspector Scott Ramsey, conducted a routine follow up inspection at Mustang Juhan Fee 26-94, at Location # 322316 in Garfield Colorado.

While there, I observed all C/A(s) from previous inspection document # 689302573 have been completed.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:	snow covered		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911 is present on well head sign		
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	flow line is locked out		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: 210267	Type: WELL	API Number: 045-06023	Status: PR
Insp. Status: PR			
Producing Well			
Comment:	producing		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700132	700700125	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5064318