

Interim Reclamation and Stormwater Inspection

January 21, 2020

Operator: Noble Energy (Operator #100322)

Location ID: 329964

Inspection Document #:

Weld County, CO

NWSW 16 4N66W 6 PM

Stephen Lunt
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name:Smits #16-1216
Location ID: 329964



Photo 1. Photo taken from the Northern perimeter of the location on January 21, 2020, facing Southeast. Photo illustrates the completion of intermediate reclamation; however, Operator did not reinstall ditch and berm BMP at the time of this inspection. Germination in interim area was high but will require a follow up to due to high amounts of mowed weedy debris.



Photo 2. Photo taken from the Southwestern corner of location on January 21, 2020, facing East. Photo illustrates no ditch and berm BMP installed after intermediate reclamation.

Inspection Photos
Location Name:Smits #16-1216
Location ID: 329964



Photo 3. Photo taken from the southern wellhead location on January 21, 2020, facing Northeast. Weed debris present on well pad; it appeared this debris moved in from off site.



Photo 4. Photo taken from the eastern perimeter of location on January 10, 2020, facing North. Photo depicts no ditch and berm BMPs installed throughout site; interim reclamation germination will require a follow up visit.