

# Interim and Stormwater Inspection

January 21, 2020

Operator: SRC Energy (Operator 10311)

Location ID: 433828

Inspection Document #:

Weld County, CO

NESE 16 4N66W

Stephen Lunt  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

**Inspection Photos**  
**Location Name: Schager /K16-64-1HN Pad**  
**Location ID: 433828**



**Photo 1.** Photo taken from the entrance of the location on January 21, 2020, facing Southeast. Photo illustrates no current track out BMPs installed. However, no track out issues were present during the time of the inspection.



**Photo 2.** Photo taken from the Northwestern corner of location on January 21, 2020, facing South. Photo illustrates no ditch and berm BMP installed after interim reclamation. No current runoff issues existed at time of inspection.



**Inspection Photos**  
**Location Name: Schager /K16-64-1HN Pad**  
**Location ID: 433828**



**Photo 3.** Photo taken from the Southwestern corner of location on January 21, 2020, facing east. No ditch and berm present at time of inspection.



**Photo 4.** Photo taken from the eastern perimeter of location on January 10, 2020, facing West.. Photo depicts no ditch and berm BMPs installed throughout site; Tank battery in background. Unconsolidated soil pile on pad site may be apart of adjacent agricultural field.

Inspection Photos  
Location Name: Schager /K16-64-1HN Pad  
Location ID: 433828



**Photo 7.** Photo taken from the Northern perimeter of location on January 21, 2020. Large Unconsolidated soil pile stored on the edge of the pad site. This soil may be in use for agricultural field adjacent to pad site.