

**Inspection Photos**  
**Location Name: Maylon Scow Pilcher #1**  
**API: 05-083-06418**



**Location ID #393155 with 200 bbl. AST.**



**Corroded bottom seam and stained soil.**



**Inspection Photos**  
**Location Name: Maylon Scow Pilcher #1**  
**API: 05-083-06418**



**Track hoe excavating containment area.**



**Containment area lined with plastic sheeting.**

**Inspection Photos**  
**Location Name: Maylon Scow Pilcher #1**  
**API: 05-083-06418**



**Load out valve opened.**



**Fluids drained from AST.**



**Inspection Photos**  
**Location Name: Maylon Scow Pilcher #1**  
**API: 05-083-06418**



**AST knocked over by track hoe.**



**Area where AST had been.**

**Inspection Photos**  
**Location Name: Maylon Scow Pilcher #1**  
**API: 05-083-06418**



**Corrosion along bottom seam of AST.**



**Excavating impacted material.**



**Inspection Photos**  
**Location Name: Maylon Scow Pilcher #1**  
**API: 05-083-06418**



**Sample location from eastern portion of excavation.**



**Sample location from western portion of excavation.**



**Inspection Photos**  
**Location Name: Maylon Scow Pilcher #1**  
**API: 05-083-06418**



**Flushing residue from AST.**



**Track hoe demolishing AST.**

**Inspection Photos**  
**Location Name: Maylon Scow Pilcher #1**  
**API: 05-083-06418**



**AST crushed into size to transport.**



**AST loaded onto flat bed trailer.**



**Inspection Photos**  
**Location Name: Maylon Scow Pilcher #1**  
**API: 05-083-06418**



**Excavated area backfilled with clean fill.**



**Project area returned to contour.**