

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/12/2020

Submitted Date:

02/12/2020

Document Number:

698701019**FIELD INSPECTION FORM**Loc ID 427389 Inspector Name: Serna, Abe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------------------------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 427384 | WELL | PR | 11/01/2019 | OW | 123-34969 | JURGENS PC B08-24D | PR |
| 427391 | WELL | TA | 10/01/2019 | OW | 123-34974 | Jurgens State B16-30D | TA |
| 427393 | WELL | PR | 11/01/2019 | OW | 123-34976 | JURGENS PC B08-23 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panels | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|----------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 6 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 3 | | |

| | | | |
|--------------------|----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 427384 Type: WELL API Number: 123-34969 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 427391 Type: WELL API Number: 123-34974 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In☒ Temporarily Abandoned

Reminder: _____

Comment: TA

Corrective Action:

Date: _____

Facility ID: 427393 Type: WELL API Number: 123-34976 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On (2/12/2020) at approximately (8:30 AM), I, (Abe Serna),
 Conducted an on-site inspection at (Jurgens State B #16-30D) (Noble Energy), at
 (Location # 427389) in (Weld) Colorado.
 While there, I observed (TA Well)
 During this inspection no compliance issues were observed.
 No follow up on this site inspection needs to be conducted.
 This is a summary of inspection report.
 Continuing Inspector Training.

sernaa

02/12/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 698701020 | Photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5065531 |