



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 286646 Type: WELL API Number: 123-24252 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On (2/12/2020) at approximately (12:50 PM), I, (Abe Serna),  Conducted an on-site inspection at (Mile High Sheep #8-35) (Nobel Energy), at  (Location # (306224) in (Weld) Colorado.  While there, I observed (PR Well)  During this inspection no compliance issues were observed.  No follow up on this site inspection needs to be conducted.  This is a summary of inspection report.  Continuing Inspector Training.</p>	sernaa	02/12/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698701044	pHOTO	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5065554">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5065554</a>