

Inspection Photos
Operator: BP America
Location #: 333708
Date: 1-31-2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of trailers stored within the northeastern working area. As this area is not needed for production operations it therefore needs be interim reclaimed.



Photo 3. View of area at the northeastern edge of project area where snow melt is forming an erosional channel flowing off of the project area where stormwater controls are not sufficient to de-energize and filter flows.



Photo 4. View of the northern project area from the northeastern corner facing westward. Revegetation appears to be progressing with grasses such as thickspike wheatgrass, western wheatgrass, and Indian ricegrass.



Photo 5. View of the reference area, comprised of pinyon juniper woodland with sagebrush and gambel oak shrubland and herbaceous understory.