

# Inspection Photos

2/11/2020

Operator: CHEVRON USA INC - 16700

Location ID: 397120

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397120



**Photo 1:** Photo taken from the east of the Location, facing southwest. Photos 1-4 provide an overview of the Location from southwest, west, northwest to North.



**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397120



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397120



**Photo 5:** Photo of well marker.



**Photo 6:** Photo taken from the north end of the Location, facing north. Photo shows risers/equipment remaining on the Location. Equipment requires removal.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397120



**Photo 7:** Photo taken from the Location. Photo shows what appears to be Russian Knapweed (*Rhaponticum repens*). This is a Colorado State listed noxious weed. *R. repens* observed throughout the Location, but is more dense within the center and northern areas of the Location.



**Photo 8:** Photo taken from Location, facing north. Photo shows *R. repens* (light brown plants) is the dominant plant observed on the Location.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397120



**Photo 9:** Photo taken from the North end of the Location, facing southeast. Photo shows *R. repens* has established throughout the location (dominant light brown plants, arrow for example).



**Photo 10:** Photo taken from the North end of the Location, facing southwest. See comments under photo 9. Photo also shows pipe equipment remaining on Location, see photo 6.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397120



**Photo 11:** Photo taken from the North end of the Location, facing west. See comments under photo 9



**Photo 12:** Photo taken from the North end of the Location, facing North. Photo shows populations/densities of *R. repens* significantly drops off once off the Location; Noxious weeds appear to be spreading from the Location to adjacent lands north. Photo also shows cable/wires observed on the northern areas adjacent to the Location.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397120



**Photo 13:** Photo taken from the southwest corner of the Location, facing northeast. Photo shows areas on the location where *R. repens* is dense (dominant light brown plants).



**Photo 14:** Photo taken from the southwest corner of the Location, facing northeast. See comments under photo 13.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397120



**Photo 15:** Photo taken from the south end of the Location, facing south. Photo shows *R. repens* was not observed within the reference areas to the south of the Location; Noxious weeds appear to be spreading from the Location to adjacent lands



**Photo 16:** Photo taken from the west end of the Location, facing west. Photo shows *R. repens* was not observed within the reference areas to the south of the Location; Noxious weeds appear to be spreading from the Location to adjacent lands

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397120



**Photo 17:** Photo taken from the south end of the Location, facing northeast. Photo shows areas on the location where *R. repens* is dense (dominant light brown plants).