

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/06/2020

Submitted Date:

02/06/2020

Document Number:

696301245**FIELD INSPECTION FORM**Loc ID 421665 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
James, Brian		bjames@hpres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421668	WELL	PR	08/01/2019	OW	123-33001	ANSCHUTZ WINDMILL 4-22H	PR
434224	WELL	PR	03/10/2014	OW	123-38036	Anschutz State 5-62-27-0857BH	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Seperator, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	03/06/2020
Type	STORAGE OF SUPL		
Comment:	Unused culverts on Southeast corner of Location		
Corrective Action:	Comply with Rule 603.f.	Date:	03/06/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused Wellhead parts at Windmill 4-22H, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	03/06/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Generator		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 3	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 2	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Glycol Unit	
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	Appear to be plumbed to surface	
Corrective Action:		Date:
Type: Emission Control Device	# 3	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	400 BBLs	STEEL AST		40.379130,-104.302350
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 421668 Type: WELL API Number: 123-33001 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 434224 Type: WELL API Number: 123-38036 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 02/05/2020 at approximately 13:18, I, Inspector Erica Petrie, conducted a Field Inspection at Anschutz 5-62-27_34 SESE, Location ID #421665 in Weld County, Colorado.</p> <p>While there, I observed Production Operations. Winter conditions, snow covered ground at the time of Inspection.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Separator, wellhead parts at Windmill 4-22H and Culverts. See photos. Comply with Rule 603.f. Corrective Action date 03.06.2020</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p> <p>Continuing Educational Inspections</p>	petrie	02/06/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402306238	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060213
696301246	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060207