

Inspection Photos  
Operator: BP America  
Location #: 326323  
Date: 1-31-2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing in portions of the outer revegetation areas with rubber rabbitbrush and western wheatgrass. However, portions of the project area remain with poor revegetation and require spot seeding.





Photo 3. View of wood and other debris identified within the project area.





Photo 4. View of musk thistles within the southern project area.





Photo 5. View of the western project area from the southwestern corner facing northward. Significant areas of bare soil remain and need to be stabilized with perennial vegetation.





Photo 6. View of the reference area, comprised of pasture in grazed/dormant vegetative condition.