

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/12/2020

Submitted Date:

02/12/2020

Document Number:

699301123**FIELD INSPECTION FORM**Loc ID 318015 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420463	WELL	SI	10/01/2019	OW	123-32586	CANNON 26-3	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 420463 Type: WELL API Number: 123-32586 Status: SI Insp. Status: SI

CementCement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: At the time of this inspection SPN Rig # 721 was rigged up over the Cannon 26-3 well prepping to pull & lay down tubing.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 2/12/2020 at approximately 1130hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Cannon 26-3 at API #05-123-32586</p> <p>in Weld County Colorado.</p> <p>While there, I observed Workover Rig prepping for a Plug & Abandon job. Form 42 PA Doc. # 402304855 was submitted on 2/6/2020 and Form 6 WAR Doc. @ 402271691 was submitted on 12/26/2019.</p> <p>At the time of this inspection SPN Rig # 721 was rigged up over the Cannon 26-3 well prepping to pull & lay down tubing.</p> <p>During this inspection no compliance issues were observed: All tanks and equipment appear to be grounded and have been ohm tested and paper work is at Kerr McGee offices. See attached photos.</p> <p>Location is partially snow covered and muddy, weather is overcast, windy and cold. I spoke with Desi Nava on site Supervisor with Kerr McGee, he told me that they moved in on 2/11/2020 and got set up and had Select energy services control emissions before work was to begin.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	02/12/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301125	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5067238