

Inspection Photos

API: 071-07593

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/14/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07593 | Date: 2/14/2020

Inspection Photos



Photo 1. There a deep erosion channel along the main access road from stormwater runoff from the road at Lat/Long:37.14482,-104.86800. This area needs to be repaired and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07593 | Date: 2/14/2020

Inspection Photos



Photo 2. Aerial image shows erosion along the road identified in the previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07593 | Date: 2/14/2020

Inspection Photos



Photo 3. The stormwater outlet from this culvert is contributing to erosion of this gully.
Lat/Long:37.14492,-104.86948.



Inspection Photos



Photo 4. Aerial image shows erosion identified in the previous photo at red arrow. It appears there is stormwater runoff from the Crazy Woman 32-27 location contributing to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07593 | Date: 2/14/2020

Inspection Photos



Photo 5. There a deep erosion channel along the access road at Lat/Long:37.14899,-104.87705.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07593 | Date: 2/14/2020

Inspection Photos



Photo 6. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07593 | Date: 2/14/2020

Inspection Photos



Photo 7. The water level at the pit is approaching 2 ft. freeboard and needs to be lowered.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07593 | Date: 2/14/2020