

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	No wellhead sign present at well		
Corrective Action:	Rule 210.b.	Date:	03/11/2020

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 295834 Type: WELL API Number: 123-25820 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On (2/11/2020) at approximately (12:15 PM), I, (Abe Serna), Conducted an on-site inspection at (McMillen G #19-20) (Noble Energy), at (Location # 310058) in (Weld) Colorado. While there, I observed (PR Well) During this inspection a compliance issues were observed. Wellhead sign need to be put on well Rule 210.b. A follow up on this site inspection needs to be conducted. This is a summary of inspection report. Continuing Inspector Training.</p>	sernaa	02/11/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402309432	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5063774
698701014	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5063770