



Well Services

P.O. Box 2641 • Grand Junction, Colorado 81502
Phone (970) 257-6100

118185

LATITUDE 39° 27' 50" N		LONGITUDE 107° 7' 56" W		RIG NO. 22
TO: Laramie Energy			DATE 2-10-20	
COMPANY FOREMAN (PRINT) John Grubich		LEASE BCU 15-0 Pad		WELL NO. BCU 22-3
<input type="checkbox"/> COUNTY Alcon	<input type="checkbox"/> STATE CO	START TIME 5:00	END TIME 3:00	

Well / Job Type

Gas Oil

Work Over Completion Swab


Operator
Mike Bell

Safety Meeting

Over head Loads

Description of Work Performed

5:00 TO 7:00 RCT SAFETY MEETING SSA
 ✓ Equipment ✓ Well PSI TAG 270 cys
 Rig down RAC PUMP AND HARD LINE
 CLEAN LOCATION MOVE EQUIPMENT
 FROM BCU 15-0 PAD TO RIFLE SHOP
 SECURE EVERYTHING SHUT DOWN
 1:30 TO 3:00 RCT



Received	Entered
----------	---------





Well Services

P.O. Box 2641 • Grand Junction, Colorado 81502
Phone (970) 257-6100

118184

LATITUDE 37° 27' 17.50" N		LONGITUDE 107° 75' 34.60" W		RIG NO. 22
TO: Laramie Energy		LEASE 800 BCU 15-0 Pad		DATE 2-7-20
COMPANY FOREMAN (PRINT) John Grubich		START TIME 5:00		WELL NO. BCU 22-3
<input type="checkbox"/> COUNTY	<input type="checkbox"/> STATE			END TIME 8:00

Well / Job Type

Gas Oil

Work Over Completion Swab

Safety Meeting

Operator

Rig up wire line
 Over head Loads and Pinch Points
 Description of Work Performed
 5:00 TO 6:30 RCT SAFETY MEETING ISA
 ✓ Equipment ✓ Wagon PSI 270 CS G
 Rig up wire line shoot pups from
 5180 TO 5364 Runs Run w/ Packer
 Set @ 4730 Rigged down (B) Trip
 1 T W/ BHA 75 STANDS PICK UP 151 IN
 10 FOOT PUP 8 FOOT 6 FOOT 2 FOOT PUP'S
 SET PACKER LUTCH ON PACKER
 PULL TENSION - Load on Hanger
 @ 4959.32 N.D. BOP N-UP Well head
 PUMP DISK @ 2700 PSI: DRAIN PUMP
 Drain ~~AND~~ Hard Line Shut down
 6:30 TO 8:00 RCT

[Redacted area]

Receiver



Well Services

P.O. Box 2641 • Grand Junction, Colorado 81502
Phone (970) 257-6100

118182

LATITUDE <i>39° 27' 17.50" N</i>		LONGITUDE <i>107° 75' 38.60" W</i>		RIG NO. <i>22</i>
TO: <i>Laramie Energy</i>			DATE <i>2-7-20</i>	
COMPANY FOREMAN (PRINT)			LEASE <i>BCU 15-0 pad</i>	WELL NO. <i>BCU 22-3</i>
<input type="checkbox"/> COUNTY <i>Mesa</i>	<input type="checkbox"/> STATE <i>COLO</i>	START TIME <i>5:00</i>	END TIME <i>8:00</i>	

Well / Job Type

Gas Oil

Work Over Completion Swab

Safety Meeting

Pinch Points High Pressure

Description of Work Performed

5:00 TO 6:30 R.C.T SAFETY Meeting ISA

✓ Well PSI 320 csg ✓ Equipment

Swivel UP 4946 W / 153 J's PUMP

Circulation Swivel in To J's 164.

PUMP Every J's Clean 164 cool NAT

PUMP Rgt Pressure UP To 1300 PSI TAP

WAIT FOR CALL PUMP 2000 PSI Broke

Circulation Swivel in 9 J's PUMP Every


Condition Tag Plug @ 5320 W / 165 J's

Circulate Bottoms UP For 30 min

Drill Plug RAC swivel Back Lay down

10 J's secure The well Shut down

6:30 TO 8:00 R.C.T





Well Services

P.O. Box 2641 • Grand Junction, Colorado 81502
Phone (970) 257-6100

118183

LATITUDE <u>39° 27' 17.50" N</u>		LONGITUDE <u>108° 7' 53.86" W</u>		RIG NO. <u>22</u>
TO: <u>Larson Energy</u>		LEASE <u>BCU 15-0 Pad</u>		DATE <u>2-8-20</u>
COMPANY FOREMAN (PRINT) <u>John Grobich</u>		START TIME <u>5:00</u>		WELL NO. <u>BCU 22-3</u>
<input type="checkbox"/> COUNTY <u>Mesa</u>	<input type="checkbox"/> STATE <u>CO</u>	END TIME <u>6:00</u>		

Well / Job Type

Gas Oil

Work Over Completion Swab

Safety Meeting

Operator

TO

RE

PER

FOR

CON

EST

FOR

PRO

TE

CO

WETLAND CONDITIONS SHOW TRIM FENCE

Description of Work Performed

5:00 TO 6:30 R.L.T. SAFETY MEETING ISA

W/ W/ P/S 0- TAGS. CSO 500 EQUIPMENT

TRIP TO PIRUP 223-0 TAG @ 5711.45

TRIP OUT LAY DOWN 27 JTS STAND BACK

75 ST AND BHA HOOK UP HARD LINE

PUMP 150 BBLs ON CSG RIG UP WIRE LINE

RVA TANK HASSETT TO 5700 FOOT

SECOND RUN LOG PLUG SET @ 5650

2 RUNS PAIR COUNT 5070 RIGGED DOWN

SECURE THE WAY SHUT DOWN

4:30 TO 6:00 R.L.T.

RECEIVED



Well Services

P.O. Box 2641 • Grand Junction, Colorado 81502
Phone (970) 257-6100

118181

LATITUDE <i>39° 27' 17.50 N</i>		LONGITUDE <i>107° 75' 39.60 W</i>		RIG NO. <i>22</i>
TO: <i>Laramie Energy</i>			DATE <i>2-6-20</i>	
COMPANY FOREMAN (PRINT)			LEASE <i>RCU 15-0 Prod</i>	
<input type="checkbox"/> COUNTY <i>Alamosa</i>		<input type="checkbox"/> STATE <i>CO</i>		WELL NO. <i>RCU 22-3</i>
			START TIME <i>5:00</i>	END TIME <i>7:30</i>

Well / Job Type

Gas Oil

Work Over Completion Swab


Safety Meeting

Operator _____

*snubbing High Pressure Ice Plugs
over head loads Pinch points*

Description of Work Performed

*5:00 TO 6:30 RCT SAFETY MEETING JSA
✓ Equipment ✓ well psi Tbg ✓ 152 JTS
Hook up Hard line up Land well
Struck 50 JTS Lay down.
SWAP Tbg FROM TRL TO PIPE RACS
Tally in w/ BHA MAI XOVER 15-D
F. NIPPER 30 JTS Pump Tbg valve 10-D
TRIP IN TO 50 JTS Land well.
Rig down snub-in Rig up Floor
Tbg Equipment Pick up Tbg to 4908-65
w/ 152 JTS Secure the well
drain PUMP and Hard line shut down
6:00 TO 7:30 RCT.*



Rec





Well Services

P.O. Box 2641 • Grand Junction, Colorado 81502
Phone (970) 257-6100

118180

LATITUDE <i>39-271750 N</i>		LONGITUDE <i>107-753860 W</i>		RIG NO. <i>22</i>
TO: <i>Laramie Energy</i>			DATE <i>2-5-20</i>	
COMPANY FOREMAN (PRINT)		LEASE <i>BCU 15-G Prod</i>		WELL NO. <i>BCU 22-3</i>
<input type="checkbox"/> COUNTY <i>Mesa</i>	<input type="checkbox"/> STATE <i>COLO</i>	START TIME <i>5:00</i>	END TIME <i>10:00</i>	

Well / Job Type

Gas Oil

Work Over Completion Swab


Safety Meeting

Operator

Weather Conditions - 13

Description of Work Performed

5:00 TO 6:30 RCT SAFETY MEETING
✓ EQUIPMENT ✓ WELL PSI 0-130
HR TRIP TO GAT EQUIPMENT START
COULD NOT GET START - 13
SHUT DOWN 8:30 TO 10:00 RCT



Received _____ Entered _____





Well Services

P.O. Box 2641 • Grand Junction, Colorado 81502
Phone (970) 257-6100

118179

LATITUDE <i>39° 27'17.50 N</i>		LONGITUDE <i>107 75 38.60 W</i>		RIG NO. <i>22</i>
TO: <i>Laramie Energy</i>			DATE <i>2-4-20</i>	
COMPANY FOREMAN (PRINT)			LEASE <i>BCU 15-0 Pad</i>	
<input type="checkbox"/> COUNTY <i>Alamosa</i>		<input type="checkbox"/> STATE <i>CO</i>		WELL NO. <i>BCU 22-3</i>
			START TIME <i>6:00</i>	END TIME <i>P 6:30</i>

Well / Job Type

Gas Oil

Work Over Completion Swab

Operator _____

Safety Meeting

over head loads

Description of Work Performed

6:00 to 7:30 RCT Safety Meeting

✓ Equipment ✓ well out 330' pad

Spot Equipment Rig UP AND WORK

AND BOP HOOK UP HAND LINE

PUMP TEST BOP TO 2500 PSI FOR 15'

Rig UP FLOW TBG EQUIPMENT.

UN SET PACKER TAKE HANGER OUT


Lay down 100 lbs Lead well.

RAC TRAYS BOP Rig UP SPUD

out Spud unit GET EVERY THING

Ready Drain Pump and Hand Line

Shut down 5' to C3 RCT



Received





Well Services

P.O. Box 2641 • Grand Junction, Colorado 81502
Phone (970) 257-6100

118178

LATITUDE 37° 27' 17.50" N	LONGITUDE 107° 75' 46.00" W	RIG NO. 22
------------------------------	--------------------------------	---------------

TO: Locust Energy	DATE 2-3-20
COMPANY FOREMAN (PRINT)	LEASE BCU 15-0 Pad
WELL NO. 22-3	END TIME 3:30
<input type="checkbox"/> COUNTY Mesa	<input type="checkbox"/> STATE CO
START TIME 5:00	

Well / Job Type

Gas Oil

Work Over Completion Swab

Safety Meeting

Operator

~~From~~ *From* ~~Lieth~~ *Lieth* ~~and~~ *and* ~~trans~~ *trans* ~~sum~~ *sum* ~~and~~ *and* ~~the~~ *the*

Description of Work Performed

From 5:00 AM Safety Meeting
 ✓ Spent 1 hour on the Mesa Form
 R/E/E Shot To BCU 15-0 Pad
 Wait For SLICK LINE FOR COURSE 418
 TO SET PLUG COULD NOT SET
 SPOT EQUIPMENT SHUT DOWN

BC 22-3 20-101

[Large yellowed area]

RUZ
AF
CL
3-

Received	Entered
----------	---------

