

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/14/2020

Submitted Date:

02/14/2020

Document Number:

689704223

FIELD INSPECTION FORM

Loc ID 335131 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269125	WELL	PR	09/01/2004	GW	045-09323	PUCKETT 33C-25	PR
293505	WELL	PR	12/31/2008	GW	045-15016	PUCKETT 33C2-25D	PR
293506	WELL	PR	12/31/2008	GW	045-15017	PUCKETT 33B-25D	PR
293507	WELL	PR	12/31/2008	GW	045-15018	PUCKETT 33A-25D	PR
293508	WELL	PR	12/31/2008	GW	045-15019	PUCKETT 33D-25D	PR

General Comment:

On Friday 02/14/2020, I, Inspector Mike Longworth, conducted a field inspection at CAERUS PICEANCE LLC PUCKETT-66S97W 25NWSE, at Location # 335131 in Garfield County, Colorado

Inspected Facilities									
Facility ID:	<u>269125</u>	Type:	<u>WELL</u>	API Number:	<u>045-09323</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:					Date:				
Facility ID:	<u>293505</u>	Type:	<u>WELL</u>	API Number:	<u>045-15016</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:					Date:				
Facility ID:	<u>293506</u>	Type:	<u>WELL</u>	API Number:	<u>045-15017</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:					Date:				
Facility ID:	<u>293507</u>	Type:	<u>WELL</u>	API Number:	<u>045-15018</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:					Date:				
Facility ID:	<u>293508</u>	Type:	<u>WELL</u>	API Number:	<u>045-15019</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Compaction						
Berms						
		Compaction				

Comment: [Limited BMP inspection due to snow cover.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704224	Inspection 689704223 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5069716