

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/19/2020

Submitted Date:

02/19/2020

Document Number:

697000571**FIELD INSPECTION FORM**Loc ID 329435 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@anadarko.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249546	WELL	SI	10/01/2019	OW	123-17349	SPAUR O 7-8	SI
417710	WELL	PR	05/01/2019	OW	123-31726	SPAUR 17-7	PR
417712	WELL	PR	07/01/2018	OW	123-31728	SPAUR 24-7	PR
417715	WELL	PR	07/01/2018	OW	123-31731	SPAUR 21-7	PR
417719	WELL	PR	07/01/2018	OW	123-31733	SPAUR 41-7	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 5		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Barbed wire topped chainlink		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire topped chainlink		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Barbed wire topped chainlink x 5		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire topped chainlink		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 5		
Comment:	Bradenhead valves are exposed at surface.		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		

Comment: Pilot is on		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment: Automation array and ECD scrubber		
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 5	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment: Meter calibration card has no information recorded. See attached photo.		
Corrective Action: Measure gas per Rule 329.		Date: 03/27/2020

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment: 210 bbls. Produced water vault is anchored.					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	OTHER	STEEL AST		,
Comment: 315 bbls					
Corrective Action:					
Date:					

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 249546 Type: WELL API Number: 123-17349 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: Facility ID: 417710 Type: WELL API Number: 123-31726 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action:  Date: Facility ID: 417712 Type: WELL API Number: 123-31728 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action:  Date: Facility ID: 417715 Type: WELL API Number: 123-31731 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action:  Date: Facility ID: 417719 Type: WELL API Number: 123-31733 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT
**Attached Documents**
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697000572	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5071825">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5071825</a>