

Inspection Photos
Location Name: SALIDA 44-26 FOLLOWUP
API#: 05-071-07675
INSP. #: 695102192



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: SALIDA 44-26 FOLLOWUP
API#: 05-071-07675
INSP. #: 695102192

Calibration Report

Report Date: 3/21/19 9:43 AM Collection Time: 3/21/19 9:52 AM

Device ID: 100107675 System: Contact # 710-646-7811
Location: SALIDA 44-26 Field: Raton Basin
State: Colorado
Producer: Evergreen Natural Gas
Purchaser: Colorado Interstate Gas

Current Date Size: 0.500 Tap Type: Flange
Pipe Size: 2.000 SP Tap Location: Crown 90 deg
Airline Pressure: 11.43 Temperature Base: 60
Pressure Base: 14.73

Plate Inspected? ☐ Yes ☒ No Dirty? ☐ Yes ☒ No Nipped? ☐ Yes ☒ No
Edges Sharp? ☐ Yes ☒ No Plate Mic'd? ☐ Yes ☒ No Warped? ☐ Yes ☒ No
Seal Ring Damaged? ☐ Yes ☒ No Pitted? ☐ Yes ☒ No Bore Downstream? ☐ Yes ☒ No
Tube Inspected? ☐ Yes ☒ No Nipped? ☐ Yes ☒ No
Dirty? ☐ Yes ☒ No Pitted? ☐ Yes ☒ No

DIFFERENTIAL PRESSURE				STATIC PRESSURE			
FOUND	LEFT	FOUND	LEFT	FOUND	LEFT	FOUND	LEFT
0.00	0.00	0.00	11.43	11.50	11.43	11.50	11.50
20.00	20.01	20.01	12.43	12.51	12.43	12.51	12.51
35.00	35.03	35.03	61.42	61.42	61.42	61.42	61.42
50.00	49.99	49.99	111.54	111.54	111.54	111.54	111.54
75.00	74.97	75.00					
100.00	100.10	100.00					

Cal. Range: 0 0 0
100 112 150

Gas Sample Taken? ☐ Yes ☒ No
H2S analysis done? ☐ Yes ☒ No
PPM: 0 %
H2O Analysis (ppm): 0 %

DP check with pressure on SP
FOUND LEFT
0 0
100 112 150

REMARKS: 37.13704, -104.84866, 2105.0m, 318°
2020/02/20 14:09:42

PHOTO 3: CALIBRATION REPORT

