

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2020

Submitted Date:

02/21/2020

Document Number:

693200563**FIELD INSPECTION FORM**Loc ID 335667 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
,		rcowden@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
470366	SPILL OR RELEASE	AC	12/31/2019		-	F23-596 Dumpline Release	EG

General Comment:

Engineering Integrity Inspection performed on February 21, 2020. In response to Form 19 Document number 402273022

Inspected FacilitiesFacility ID: 470366 Type: SPILL OR API Number: - Status: AC Insp. Status: EG**Flowline**

#1	Type: Dump Line	1 of Lines	
----	-----------------	------------	--

Flowline DescriptionFlowline Type: Dump LineSize: 2"Material: Carbon SteelVariance: NoAge: NewContents: Produced WaterIntegrity SummaryFailures: OtherSpills: YesRepairs Made: YesCoatings: Yes ExternalH2S: NoCathodic Protection: NoPressure TestingWitnessed: YesTest Result: PassCharted: YesCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment:

A failed dumpline was discovered during a pressure test. The line was immediately de-energized and taken out of service.

Repairs made and pressure test performed. 30-minute test start pressure 204psi and ended with 203psi

Provide Root Cause when information becomes available. Via Form 4 and email to Western Integrity inspector

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200564	photo1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5074534
693200565	photo2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5074535