

Banta Ridge 10-18-1-103

API: 05-103-10410

Inspection: 700400146



**Photo 1. Location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Banta Ridge 10-18-1-103

API: 05-103-10410

Inspection: 700400146



39.96478, -108.99173, 5793.5ft, 88°

02/21/2020 11:44:14 AM

Photo 2. Tanks.




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Banta Ridge 10-18-1-103

API: 05-103-10410

Inspection: 700400146



**Photo 3. Pump jack.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Banta Ridge 10-18-1-103

API: 05-103-10410

Inspection: 700400146

Gas leak



Photo 4. Gas leak at pump jack motor.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Banta Ridge 10-18-1-103

API: 05-103-10410

Inspection: 700400146



Photo 5. Battery sign.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources