

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/24/2020

Submitted Date:

02/24/2020

Document Number:

693200566

### FIELD INSPECTION FORM

Loc ID 335600 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
Caerus		rcowden@caerusoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
471747	SPILL OR RELEASE	AC	02/21/2020		-	B26 dumpline B26	EG

**General Comment:**

Engineering Integrity Inspection performed on February 24, 2020. In response to Form 19 Document number 402316507

**Inspected Facilities**

Facility ID: 471747 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

**Flowline**

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel  
 Variance: No Age: 1-5 Yrs Contents: Produced Water

Integrity Summary

Failures: Other Spills: Yes Repairs Made: Yes  
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: No Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: operator noted on form 19: A lease operator was conducting pressure testing on the B26 produced water dumpline. The lease operator noted a failed pressure test on the dumpline. This dumpline line was last pressure tested on January 15, 2020.

The flowline is locked out and tagged out,

Provide Root Cause when information becomes available. Via Form 4 and email to Western Integrity inspector

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200567	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5075778">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5075778</a>