



**Inspection Photos**  
**Location Name: Anschutz – O'Brien 5-61-33-57H**  
**Location ID: 430466**



**Photo 1 – Pumping Unit**



**Photo 2 – Unused Polish Rod at Pumping Unit**





**Inspection Photos**  
**Location Name: Anschutz – O'Brien 5-61-33-57H**  
**Location ID: 430466**



**Photo 3 – Unmarked Risers in the SE corner of location**



**Photo 4 – Unmarked Risers on the Eastside of location**





**Inspection Photos**  
**Location Name: Anschutz – O'Brien 5-61-33-57H**  
**Location ID: 430466**



**Photo 5 – Unmarked Risers on the Eastside of location**



**Photo 6 – Condensate Tank missing Capacity**

