

Inspection Photos

Location Name: RUSTED ROOT 12-25 FOLLOWUP

API#: 05-071-09175

INSP. #: 695102207



Colorado Oil & Gas Conservation Commission
37.14395, -104.8458, 2141.0m, 195°
2020/02/24 15:03:48

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.14347, -104.84589, 2150.0m, 197°
2020/02/24 15:06:01

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: RUSTED ROOT 12-25 FOLLOWUP
API#: 05-071-09175
INSP. #: 695102207

Calibration Report

Report Date: 10/2/19 10:32 AM
Collection Time: 10/2/19 9:41 AM

Device ID: 100109175
Location: Rusted Root 12-25

System: Contact # 719-846-7898
Field: Raton Basin
State: Colorado
Producer: Evergreen Natural Resources
Purchaser: Colorado Interstate Gas

Section 4: Setup

Current Plate Size: 0.375
Pipe Size: 2.063
Atmos. Pressure: 11.33
Pressure Base: 14.73

Tap Type: Flange
SP Tap Location: Up Stream
Temperature Base: 60

Specific Gravity: 0.50

Plate Inspected? ☐ Yes ☒ No
Edges Sharp? ☐ Yes ☒ No
Seal Ring Damaged? ☐ Yes ☒ No

Dirty? ☐ Yes ☒ No
Plate Mic'd? ☐ Yes ☒ No
Pitted? ☐ Yes ☒ No

Nicked? ☐ Yes ☒ No
Warped? ☐ Yes ☒ No
Bevel Downstream? ☐ Yes ☒ No

Section 5: Tube Tests

Tube Inspected? ☐ Yes ☒ No
Dirty? ☐ Yes ☒ No
Pitted? ☐ Yes ☒ No

Section 6: Pressure Tests

DIFFERENTIAL		STATIC PRESSURE		CORRECTED	
FOUNDED	LEFT	FOUNDED	LEFT	FOUNDED	LEFT
0.00	0.01	0.00	0.01	11.33	11.33
100.00	100.02	100.00	100.02	111.33	111.33
75.00	75.00	75.00	75.00	81.33	81.34
50.00	50.00	50.00	50.00	61.33	61.34
25.00	25.00	25.00	25.00	41.33	41.34
2.00	1.99	2.00	1.99	21.33	21.34

Cal Range: 0 to 150
Gas Sample Taken: ☐ Yes ☒ No
K125 analysis done: ☐ Yes ☒ No
PPM or %: ☐ Yes ☒ No
K125 Analysis Done: ☐ Yes ☒ No

DP (check valve pressure on SD)
FOUNDED LEFT

REMARKS

PHOTO 1: LOCATION

