

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/20/2020

Submitted Date:

02/24/2020

Document Number:

688800678**FIELD INSPECTION FORM**Loc ID 313577 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46685Name of Operator: KINDER MORGAN CO2 CO LPAddress: 1001 LOUISIANA ST SUITE 1000City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Jardine, Jennifer		jjardine@blm.gov	
Heil, John		john.heil@state.co.us	
Hannigan, Michael	(970) 882-5532	CO2Source_Regulatory@kindermorgan.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224522	WELL	PR	03/07/2018	GW	083-06587	YB 4	EI

General Comment:

On February 20, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan YB-4. For the most recent field inspection report of this facility, please refer to document #685301793.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Good Housekeeping:			
Type	TRASH		
Comment:	Discarded sign near rig anchor marker.		
Corrective Action:	Comply with Rule 603.f.	Date:	03/05/2020

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Perimeter fencing.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Steel pipe barricade fencing around flowline vent and cathodic protection station.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			

Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	224522	Type:	WELL	API Number:	083-06587	Status:	PR	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On February 20, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan YB-4. For the most recent field inspection report of this facility, please refer to document #685301793.	hughesjo	02/24/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800679	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5076124